



**Application
Parameters**

Duct

Point Measurement

Output Signal Active CO₂:

DC 0...5 V, DC 0...10 V	22DC-11			
DC 0...5 V, DC 0...10 V	22DC-110L			
DC 0...5 V, DC 0...10 V	22DCK-11			
DC 0...5 V, DC 0...10 V	22DCM-11			
DC 0...5 V, DC 0...10 V	22DCV-11			
DC 0...5 V, DC 0...10 V	22DTC-11			With LCD-Display:
DC 0...5 V, DC 0...10 V	22DTM-11		DC 0...5 V, DC 0...10 V	22DTM-1106

4...20 mA	22DC-13	
4...20 mA	22DTC-13	
Modbus	22DTM-15	
BACnet	22DTM-16	